


### Plate cutting

Have at least 1 cm of mounting tape outside the perimeter of the board to prevent edge lift. Plates that are trimmed on soft backing can create burrs on the base allowing solvent/cleaner/ink to migrate between the plate and the tape.



Check the condition of the cutting blade. Corners that are cut at 90° angles are more prone to tearing or dismantling. If possible, round the corners. Esko Kongsberg table helps with this problem.

